



Libraries and Learning Services

# University of Auckland Research Repository, ResearchSpace

## Version

This is the Accepted Manuscript version. This version is defined in the NISO recommended practice RP-8-2008 <http://www.niso.org/publications/rp/>

## Suggested Reference

Dizhur, D., Bailey, S., Griffith, M., & Ingham, J. (2015). Earthquake Performance of Two Vintage URM Buildings Retrofitted Using Surface Bonded GFRP: Case Study. *Journal of Composites for Construction*, 19(5) Article number 05015001. doi: [10.1061/\(ASCE\)CC.1943-5614.0000561](https://doi.org/10.1061/(ASCE)CC.1943-5614.0000561)

## Copyright

Items in ResearchSpace are protected by copyright, with all rights reserved, unless otherwise indicated. Previously published items are made available in accordance with the copyright policy of the publisher.

For more information, see [General copyright](#), [Publisher copyright](#), [SHERPA/RoMEO](#).

1 **Earthquake Performance of Two Vintage URM Buildings Retrofitted Using**  
2 **Surface Bonded GFRP: Case Study**

3 Dmytro Dizhur<sup>1</sup>, Sara Bailey<sup>2</sup>, Michael Griffith<sup>3</sup> and Jason Ingham<sup>4</sup>

4 **CE Database Subject Headings: Fiber reinforced polymer, Rehabilitation, Masonry,**  
5 **Earthquake resistance, Structures**

6 *(1) Research Fellow, Department of Civil & Environmental Engineering, University of Auckland, Private Bag*  
7 *92019, Auckland 1010, New Zealand, ddiz001@aucklanduni.ac.nz*

8 *(2) Student Researcher, Department of Civil & Environmental Engineering, University of Auckland, Private*  
9 *Bag 92019, Auckland 1010, New Zealand, sbai063@aucklanduni.ac.nz*

10 *(3) Professor, School of Civil, Environmental and Mining Engineering, University of Adelaide, Adelaide,*  
11 *Australia, mcgrif@civeng.adelaide.edu.au*

12 *(4) Professor, Department of Civil & Environmental Engineering, University of Auckland, Private Bag 92019,*  
13 *Auckland 1010, New Zealand, j.ingham@auckland.ac.nz*

14 **ABSTRACT**

15 As part of a seismic retrofit scheme, surface bonded Glass Fiber Reinforced Polymer (GFRP)  
16 fabric was applied to two unreinforced masonry (URM) buildings located in Christchurch, New  
17 Zealand. The unreinforced stone masonry Girls' High School and the unreinforced clay brick  
18 masonry Shirley Community Centre were retrofitted using surface bonded GFRP in 2007 and  
19 2009 respectively. Much of the knowledge on seismic performance of GFRP retrofitted URM  
20 was previously assimilated from laboratory-based experimental studies having controlled  
21 environments and loading schemes. The 2010/2011 Canterbury earthquake sequence provided a  
22 rare opportunity for the GFRP retrofit applied to two vintage URM buildings to be evaluated  
23 and the performance when subjected to actual design-level earthquake induced shaking to be  
24 documented. Both GFRP retrofits were found to be successful in preserving architectural  
25 features within the buildings as well as maintaining the structural integrity of the URM walls.  
26 Successful seismic performance was based on comparisons made between the GFRP retrofitted  
27 Girls' High School building and the adjacent non-retrofitted Boys' High School building, as well

28 as comparison between the GFRP retrofitted and non-retrofitted walls of the Shirley  
29 Community Centre building. Based on detailed post-earthquake observations and investigations  
30 the GFRP retrofitted URM walls in the subject buildings exhibited negligible to minor levels of  
31 damage without delamination, whereas significant damage was observed in comparable non-  
32 retrofitted URM walls.

## 33 **INTRODUCTION**

34 Most of New Zealand's URM building stock was constructed prior to 1935 and was typically  
35 designed with little or no consideration for lateral loads (Russell and Ingham 2010). In response  
36 to these deficiencies the New Zealand Building Act 2004 (NZ Parliament 2004) requires  
37 territorial authorities to adopt policies on retrofitting or demolition of buildings having deficient  
38 earthquake strength, and because many vintage URM structures are considered to be either  
39 'earthquake prone' (satisfying 1/3 of current earthquake loading standards) or 'earthquake risk'  
40 (satisfying between 1/3 and 2/3 of current earthquake loading standards) these buildings must  
41 be either seismically retrofitted or demolished within timeframes set by the territorial authorities  
42 (NZSEE 2006), with the former scenario being favourable as many of these URM buildings are  
43 listed on the Register of the New Zealand Historic Places Trust. One retrofit option is the  
44 application of fibre reinforced polymers (FRP).

45 Fiber reinforced polymers consist of carbon, glass or aramid fibres embedded in a resin matrix to  
46 produce a high tensile strength, lightweight material. FRP has been commercially available since  
47 the 1940's and was originally used to improve the performance of vehicles for space exploration  
48 and air travel. Research on the use of FRP as a building material began in the late 1980's as it  
49 became more economically viable for structural engineering applications in concrete, masonry  
50 and timber materials (Bakis et al. 2002; Raftery and Whelan 2014). In addition to high tensile  
51 strength and low weight, FRP material is corrosion resistant and is simple to apply. The resulting

52 thickness of FRP in structural applications is typically less than 3 mm (ElGawady and Lestuzzi  
53 2004; Shrive 2006) which can be covered using plaster and other coatings to produce a desirable  
54 finish. These aforementioned attributes have resulted in FRP being perceived favourably as a  
55 seismic retrofit solution for existing buildings with deficient capacity and as an alternative to the  
56 provision of reinforced shotcrete or supplementary steel or reinforced concrete structure. Much  
57 of the research previously completed on FRP for structural engineering applications was focused  
58 on retrofit of deficient reinforced concrete frame structures. However, due to a vast number of  
59 earthquake vulnerable unreinforced masonry (URM) buildings worldwide, the use of FRP as a  
60 retrofit solution for URM structures has received increasing attention.

61 Past research undertaken on URM walls retrofitted using surface bonded Glass (G) FRP to  
62 enhance the in-plane seismic performance reported an increase in shear strength (Tumialan et al.  
63 ; Albert et al. 2001; Gustavo et al. 2003; Stratford et al. 2004; ElGawady et al. 2005b; ElGawady  
64 et al. 2005a; Marcarì et al. 2007; Moon et al. 2007; Mosallam 2007; Alcaïno and Santa-Maria  
65 2008; Mahmood and Ingham 2011; Dizhur et al. 2013; Zhou et al. 2013). The general consensus  
66 from previous research is that application of surface bonded FRP materials reduces the effects of  
67 URM material variability and favourably improves the ductile behaviour of retrofitted URM  
68 walls. ElGawady et al. (2006) previously reported that the lateral resistance of URM  
69 walls retrofitted using surface bonded FRP was improved by a factor ranging between 1.3  
70 and 2.9. When the FRP was detailed to cross the critical failure plane, the application of  
71 surface bonded FRP postponed the onset of in-plane failure of diagonal step cracking and  
72 also postponed the onset of rocking (flexural failure) and bed joint sliding. Collapse of tested  
73 walls was also delayed when subjected to large lateral wall deformations and the FRP fabric  
74 reduced the risk of falling debris, alleviating the potential hazard of injury to the public in  
75 the vicinity of the building (ElGawady et al. 2006).

76 Apart from a small number of previously reported seismic performance of real FRP retrofitted  
77 masonry structures (Foraboschi 2013), much of the knowledge on the seismic performance of  
78 GFRP retrofitted URM was previously assimilated from laboratory-based experimental studies  
79 having controlled environments and loading schemes. The 2010/2011 Canterbury earthquake  
80 sequence provided a rare opportunity for the GFRP retrofit applied to vintage URM walls of the  
81 Girls' High School and the Shirley Community Centre to be evaluated and the performance  
82 when subjected to actual earthquake induced shaking to be documented. Detailed earthquake  
83 damage observations, qualitative comparisons and assessment of design loads relative to  
84 experienced level of earthquake induced shaking are presented herein for the two subject  
85 buildings.

## 86 **GFRP RETROFIT DETAILS**

### 87 **Girls' High School (GHS) Building**

88 A detailed history of the Arts Centre of Christchurch was previously reported by Bailey et al.  
89 (2014). The specific building of interest within the Arts Centre precinct is the Girls' High School  
90 (hereafter GHS) building (see **Figure 1**), which was constructed in 1878 using unreinforced  
91 masonry consisting of Port Hills volcanic basalt stones and limestone facings in the same Gothic  
92 style as adopted for the previously completed Arts Centre buildings (Bailey et al. 2014).  
93 Additions to the building were constructed in 1893, mainly consisting of clay brick masonry  
94 construction faced with unreinforced stone masonry finish, and further additions were made in  
95 1902.

96 Seismic retrofit of the GHS building began in the 1980's with bracing of the roof diaphragm  
97 being instituted throughout the structure. In 2007 the GHS building underwent further seismic  
98 retrofit, with the application of a GFRP retrofit completed in conjunction with diaphragm

99 improvements and the addition of structural steel framework. The use of single sided surface  
100 bonded GFRP sheets was considered to be a suitable retrofit option due to the presence of  
101 URM shear walls on which extensive areas of GFRP fabric could be adhered to. In literature it is  
102 stated that single sided surface bonded GFRP sheets result in less effective improvement. In wall  
103 components found in real buildings, where restraint of all the wall edges is typically provided by  
104 the wall-diaphragm connections and/or continuity of the wall and the single sided application of  
105 GFRP sheets is of lesser concern. As can be seen in **Figure 2**, the selected walls for GFRP  
106 retrofit application provided continuous areas with few perforations. The ability for the GFRP  
107 retrofit to be applied to specific targeted areas of weakness in order to achieve the increased  
108 shear and flexural strength to contribute to the overall strength of the structure was  
109 advantageous and made GFRP an economically viable retrofit solution for the GHS building.  
110 Installation of diaphragm-to-wall anchorages and the addition of supplementary steel framework  
111 were implemented in order to suppress other failure mechanisms.

112 Installation of the GFRP retrofit involved removal of the internal wall linings and the use of  
113 structural putty filler applied to the underlying volcanic basalt. Application of additional putty  
114 filler was necessary in order to minimise sharp edges or protrusions that would otherwise cause  
115 voids under the GFRP sheets, as well as to minimise the potential for stress concentrations to  
116 the GFRP fibers and to enhance adhesion to the masonry surface. Approximately 200 m<sup>2</sup> of  
117 unidirectional woven GFRP fabric was applied, with the following technical product  
118 specifications: areal weight of 935±47 g/m<sup>2</sup>, fiber density of 2.56 g/m<sup>3</sup>, fabric design thickness  
119 of 0.36 mm; fibre tensile strength of 2.3 kN/mm<sup>2</sup> (nominal) and tensile elastic modulus of fibers  
120 of 76 GPa. The GFRP retrofit was designed with reference to ACI 440.2R-02 (2002) and the  
121 design guidelines provided by the GFRP manufacturer. Sufficient quantity of GFRP layers was  
122 applied in order to meet the required loading levels. The applied GFRP layers were not  
123 considered as upper limit and potential for higher strengthening actions existed. **Figure 3a**

124 shows GFRP retrofit application by an accredited contractor prior to the re-lining of the walls to  
125 achieve a close-to-original finish. A first layer of GFRP sheets was applied followed by  
126 installation of GFRP splay anchors into holes drilled into the masonry. Splay anchors were  
127 installed in order to provide adequate connection between the GFRP fabrics and the masonry,  
128 and to minimise delamination (see **Figure 2e** and **Figure 3b**) and were typically spaced at  
129 approximately 500 mm centres around the GFRP sheet perimeter. A second layer of GFRP  
130 sheets was then applied.

### 131 **Shirley Community Centre (SCC) Building**

132 Shirley Community Centre (hereafter SCC) is a single storey building that was constructed in  
133 1915 using unreinforced clay brick masonry, to be originally used as the Shirley Primary School.  
134 The building had a hipped roof and was constructed in the Georgian style with large and regular  
135 fenestrations as show in **Figure 4**. The perimeter walls of the SCC building consisted of two leaf  
136 thick solid red clay brick masonry with a veneer layer of yellow clay bricks on the exterior surface  
137 that was separated with a 50 mm wide air cavity.

138 Seismic improvement work was undertaken on the SCC building in 2009. In order to enhance  
139 the rocking and shear capacity of the URM piers along the interior wall of the northern wing  
140 corridor of the SCC building, seven individual wall areas were strengthened using surface bonded  
141 GFRP. Single layer GFRP sheets were applied onto the full height of each individual wall area  
142 with approximately 60 m<sup>2</sup> of fabric in total being applied throughout the SCC building. GFRP  
143 sheets used in the SCC building had the same technical product specifications as the sheets used  
144 in the GHS building. The GFRP retrofit was applied to the corridor side of the walls only, with  
145 the retrofit locations shown in **Figure 5**.

146 Prior to the application of GFRP fabric, the original rendering plaster was removed from the  
147 application area and the wall surface was made smooth and as flat as possible. Installation of the

148 GFRP fabric prior to reapplication of the rendering plaster is illustrated in **Figure 6**. The  
149 application of one layer of GFRP sheets was predominantly intended to improve the shear  
150 capacity of the individual piers. To increase the rocking capacity of the piers, approximately  
151 12 mm diameter GFRP anchor rods were embedded 300 mm deep at 150 mm centres into the  
152 concrete strip foundation beams. A localised strip of the timber flooring was removed to allow  
153 the anchor rods to be drilled and epoxied into the concrete foundation beam. The top ends of  
154 the GFRP anchor rods were fanned out and positioned at the base of each retrofitted pier and  
155 oversplayed with the aforementioned GFRP sheets (see **Figure 6c**). In addition to the GFRP  
156 anchor rods, the rocking capacity of the piers was further enhanced by providing extra 150 mm  
157 wide strips of GFRP fabric bonded along the full height of the pier edges (see **Figure 6b** and **c**).

158 The out-of-plane stability to the perimeter walls of the SCC building was enhanced by using  
159 vertically oriented steel hollow sections as strong backs regularly fixed to the URM walls. To  
160 ensure sufficient lateral load resistance in the north-south direction, a reinforced concrete shear  
161 wall was also added at the location shown in **Figure 5**. The external veneer brick layer was  
162 secured to the main wall using stainless steel helical veneer ties installed at regular spacing.

## 163 **CANTERBURY EARTHQUAKES**

164 The Canterbury earthquake sequence began on 4<sup>th</sup> September 2010 and was followed by a large  
165 number of aftershocks including the more damaging 22<sup>nd</sup> February 2011  
166 Christchurch earthquake. Bailey et al. (2014) have reported the main events of the earthquake  
167 sequence and their significance to the Arts Centre of Christchurch. Further information relevant  
168 to the general performance of URM buildings was also previously reported by Dizhur et al.  
169 (2010), Dizhur et al. (2011), Senaldi et al. (2012) and Moon et al. (2014).

170 The 22<sup>nd</sup> February 2011 tremor, although of shorter duration, had peak ground accelerations  
171 (PGA) equivalent to or of greater intensity than that considered in new building design standards



172 at the time (Bradley et al. 2014) . Christchurch Hospital (CHHC) was identified as the location of  
173 the closest strong motion recording station to the Christchurch Arts Centre, where a PGA of  
174 0.17g and 0.37g was recorded, with the principal motion felt in the east-west direction during the  
175 4<sup>th</sup> September 2010 and 22<sup>nd</sup> February 2011 earthquakes respectively (Bradley et al. 2014). The  
176 design level PGA for new construction at the time of the earthquake was equivalent to 0.36g  
177 (Standards Association of New Zealand 2004), but it is understood that the design PGA used at  
178 the time of the retrofit for the GHS building was 1/3 of the 0. 36g earthquake loading specified  
179 in the loadings code at the time.

180 Shirley Library (SHLC) was identified as the location of the closest (less than 1 km) strong  
181 motion recording station to the SCC building, where a PGA of 0.18g and 0.33g were recorded  
182 during the 4th September 2010 and 22nd February 2011 earthquakes respectively (Bradley et al.  
183 2014). The retrofit of the SCC building was designed to 2/3 of the loading standard (Standards  
184 Association of New Zealand 2004) based on NZSEE (2006) recommended loading at the time  
185 of the design in 2007, with a horizontal design PGA of 0.25g.

## 186 **PERFORMANCE OF GFRP RETROFITTED WALLS**

### 187 **Performance of GHS Building**

188 The interior plasterboard covering the GFRP retrofit was removed following the 22<sup>nd</sup> February  
189 2011 earthquake in test locations throughout the GHS building in order to observe the  
190 performance of the retrofit. From the exposed locations there was no evidence to suggest  
191 delamination of the GFRP from the stone masonry substrate. Minor cracks were observed in the  
192 interior plasterboard in localised areas. One of these areas was around the chimney that acted as  
193 a heavy weight cantilever, resulting in significant cracking throughout the surrounding area.

194 Overall, the GFRP retrofit contributed to the preservation of a number of architectural features,  
195 such as the pressed ceiling detailing, with the building requiring only minor repair. Although the  
196 retrofit of the GHS building significantly improved the seismic performance of the building and  
197 resulted in an overall global minimisation of structural damage, the building's connection and  
198 proximity to the substantially damaged nearby West Lecture building resulted in the GHS  
199 building having limited access while the remainder of the centre underwent repair and  
200 stabilisation work. The Boys' High School building is located within the same complex as the  
201 GHS building and was analysed in detail in order to provide a benchmark comparison for the  
202 performance of the GFRP retrofit. The construction of these two buildings was completed at  
203 approximately the same time (Bailey et al. 2014) and as can be seen from the aerial view of  
204 the Arts Centre (see elevation view GHS **Figure 7**), the two buildings have similar features  
205 and layouts. **Figure 8** shows selective examples of damage in the shear walls that was  
206 identified throughout the Boys' High School building and **Figure 9** shows comparison images of  
207 the GHS building. The Boys' High building had no FRP installed and a number of areas were  
208 identified where the retrofit may have been beneficial through increasing the shear capacity and  
209 integrity of some lateral load resisting URM walls. Although a number of minor cracking  
210 locations caused by large shear forces and differential movement between floors was identified  
211 throughout the GHS building, the level of earthquake damage was minimal when compared to  
212 that observed in the Boys' High building.

213 Due to the successful performance of the GFRP retrofit in the GHS building, the Old Registry  
214 building that is located at the northwest side of the Arts Centre Complex has since undergone  
215 FRP retrofit as part of the post-earthquake repairs and rehabilitation that was completed in mid-  
216 2013.

## 217 **Performance of SCC Building**

218 The SCC building performed well during the 4<sup>th</sup> September 2010 earthquake without incurring  
219 significant earthquake damage, and following the earthquake the building was reoccupied after an  
220 initial engineering inspection. Minor cracking was observed at the ceiling level and at the wall-  
221 ceiling corners. There was no visible cracking at the location of surface bonded GFRP sheets, as  
222 shown in **Figure 10a**, although there were visible cracks in the plaster in the external piers along  
223 the corridor running east-west in the south part of the building. Minor horizontal cracking and  
224 spalling of the plaster layer was observed at the northeast wall of the SCC building. In addition, a  
225 minor step-wise crack through the veneer layer was observed in the southwest corner of the SCC  
226 building.

227 Following the 22<sup>nd</sup> February 2011 Christchurch earthquake and subsequent aftershocks, the SCC  
228 building sustained considerably greater damage in comparison to that observed following the 4<sup>th</sup>  
229 September 2010 earthquake. However, most of the wall segments that were retrofitted using  
230 GFRP fabric overlays sustained no to minimal cracking, as shown in **Figure 10b**. In some cases  
231 (see **Figure 10c**) a vertical crack was developed at the locations where the GFRP sheets  
232 terminated, indicating minor relative movement. In two out of seven piers where GFRP fabric  
233 was applied there was minor horizontally oriented cracking observed, as shown in **Figure 10d**,  
234 with the crack widths measured as approximately 0.25 mm and predominantly extending the  
235 entire width of the wall segment. In the same wall segments, horizontally oriented hairline  
236 cracking was also observed on the opposite side of the wall to where GFRP sheets were applied  
237 (see **Figure 10e**). In places where relative movement of the timber floor diaphragm occurred the  
238 GFRP fabric was inspected for visual signs of delamination, as shown in **Figure 10f**. Movement  
239 of the timber floor diaphragm relative to the URM walls was attributed to moderate liquefaction  
240 that was observed on site.

241 In many cases the URM walls in the SCC building that had no GFRP fabric sustained significant  
242 irreparable earthquake damage. Perforated corridor external walls that were directly opposite to  
243 the GFRP retrofitted walls along the east wing of the SCC building provided a good benchmark  
244 comparison of performance. The corridor external walls suffered significant damage due to  
245 rocking and sliding failure of the URM piers (see **Figure 11a and d**). Significant shear cracking  
246 and disintegration of masonry was observed in solid URM shear walls in other parts of the SCC  
247 building as shown in **Figure 11**. Due to the severe damage to the unretrofitted URM walls and  
248 differential settlement of the building foundations, repair of the building was deemed  
249 uneconomical and the SCC building was subsequently demolished.

## 250 **CONCLUSIONS**

251 The 2010/2011 Canterbury earthquake sequence provided an opportunity for the performance  
252 of surface bonded GFRP retrofit applied to two vintage URM buildings to be evaluated. GFRP  
253 retrofits were found to be successful in preserving architectural features within the buildings as  
254 well as maintaining the structural integrity of the URM walls. Successful seismic performance  
255 was based on comparisons made between the GFRP retrofitted Girls' High School building and  
256 the adjacent non-retrofitted Boys' High School building, as well as comparison between the  
257 GFRP retrofitted and non-retrofitted walls of the Shirley Community Centre building. Based on  
258 detailed post-earthquake observations and investigations the GFRP retrofitted URM walls in the  
259 subject buildings exhibited negligible to minor levels of damage without delamination, whereas  
260 significant damage was observed in comparable non-retrofitted URM walls.

## 261 **ACKNOWLEDGEMENTS**

262 The authors wish to thank The Arts Centre of Christchurch for providing permission to report  
263 the findings contained herein, Sika (NZ) Ltd and BBR Contech for details associated with the

- 264 supply and installation of the GFRP retrofit, and Holmes Consulting Group for details of the
- 265 GRFP retrofit design.

- 267 ACI-440.2R-02 (2002). "Guide for the design and construction of externally bonded FRP systems for  
268 strengthening concrete structures." Michigan, USA, MCP.
- 269 Albert, M., A. Elwi and J. Cheng (2001). "Strengthening of Unreinforced Masonry Walls Using FRPs."  
270 *Journal of Composites for Construction* **5**(2): 76-84.
- 271 Alcaino, P. and H. Santa-Maria (2008). "Experimental Response of Externally Retrofitted Masonry  
272 Walls Subjected to Shear Loading." *Journal of Composites for Construction* **12**(5): 489-498.
- 273 Bailey, S., Dizhur, D., Trowsdale, J., Griffith, M. C., & Ingham, J. M. (2014). "Performance of  
274 posttensioned seismic retrofit of two stone masonry buildings during the Canterbury  
275 Earthquakes". In ASCE Journal of Performance of Constructed Facilities, pp.1–11.  
276 [http://dx.doi.org/10.1061/\(ASCE\)CF.1943-5509.0000603](http://dx.doi.org/10.1061/(ASCE)CF.1943-5509.0000603)
- 277 Bakis, C., L. Bank, V. Brown, E. Cosenza, J. Davalos, J. Lesko, A. Machida, S. Rizkalla and T.  
278 Triantafillou (2002). "Fiber-Reinforced Polymer Composites for Construction—State-of-the-  
279 Art Review." *Journal of Composites for Construction* **6**(2): 73-87.
- 280 Bradley, B. A., M. C. Quigley, R. J. Van Dissen and N. J. Litchfield (2014). "Ground Motion and Seismic  
281 Source Aspects of the Canterbury Earthquake Sequence." *Earthquake Spectra* **30**(1): 1-15.
- 282 Dizhur, D., M. Griffith and J. Ingham (2013). "In-Plane Shear Improvement of Unreinforced Masonry  
283 Wall Panels Using NSM CFRP Strips." *Journal of Composites for Construction* **17**(6):  
284 04013010.
- 285 Dizhur, D., J. M. Ingham, L. Moon, M. C. Griffith, A. Schultz, I. Senaldi, G. Magenes, J. Dickie, S. Lissel,  
286 J. Centeno, C. Ventura, J. Leite and P. Lourenco (2011). "Performance of masonry buildings  
287 and churches in the 22 February 2011 Christchurch earthquake." *Bulletin of New Zealand  
288 Society for Earthquake Engineering* **44**(4): 279-297.
- 289 Dizhur, D. I., N. Knox, C. Lumantarna, R. Ingham, J. M. (2010). "Performance of Unreinforced and  
290 Retrofitted Masonry Buildings during the 20120 Darfield Earthquake." *Bulletin of the New  
291 Zealand Society for Earthquake Engineering* **43**(4): 321-339.
- 292 ElGawady, M. A. and P. Lestuzzi (2004). "A review of Retrofitting of Unreinforced Masonry Walls  
293 Using Composites." *Advanced Composite Materials in Bridges and Structures*.
- 294 ElGawady, M. A., P. Lestuzzi and M. Badoux (2005a). "Aseismic retrofitting of unreinforced masonry  
295 walls using FRP." *Composites Part B: Engineering* **37**(2–3): 148-162.
- 296 ElGawady, M. A., P. Lestuzzi and M. Badoux (2005b). "In-plane seismic response of URM walls  
297 upgraded with FRP." *Journal of Composites for Construction* **9**(6): 524-535.
- 298 ElGawady, M. A., P. Lestuzzi and M. Badoux (2006). "Aseismic retrofitting of unreinforced masonry  
299 walls using FRP." *Composites Part B* **37**(2): 148-162.
- 300 Foraboschi, P. (2013). "Church of San Giuliano di Puglia: Seismic repair and upgrading." *Engineering  
301 Failure Analysis* **33**(0): 281-314.
- 302 Gustavo, J., N. Galati and A. Nanni (2003). "Fiber-reinforced polymer strengthening of unreinforced  
303 masonry walls subject to out-of-plane loads." *ACI Structural Journal* **100**(3): 321-329.
- 304 Mahmood, H. and J. M. Ingham (2011). "Diagonal compression testing of FRP-retrofitted  
305 unreinforced clay brick masonry wallettes." *Journal of Composites for Construction* **15**(5):  
306 810-820.
- 307 Marcari, G., G. Manfredi, A. Prota and M. Pecce (2007). "In-plane shear performance of masonry  
308 panels strengthened with FRP." *Composites Part B: Engineering* **38**(7–8): 887-901.
- 309 Moon, F. L., T. Yi, R. T. Leon and L. F. Kahn (2007). "Testing of a Full-Scale Unreinforced Masonry  
310 Building Following Seismic Strengthening." *Journal of Structural Engineering* **133**(9): 1215-  
311 1226.
- 312 Moon, L., D. Dizhur, I. Senaldi, H. Derakhshan, M. Griffith, G. Magenes and J. Ingham (2014). "The  
313 Demise of the URM Building Stock in Christchurch during the 2010–2011 Canterbury  
314 Earthquake Sequence." *Earthquake Spectra* **30**(1): 253-276.

315 Mosallam, A. S. (2007). "Out-of-plane flexural behavior of unreinforced red brick walls strengthened  
316 with FRP composites." *Composites Part B: Engineering* **38**(5-6): 559-574.  
317 New Zealand Society for Earthquake Engineering (NZSEE). (2006). "Assessment and improvement of  
318 the structural performance of buildings in earthquakes."  
319 [http://www.nzsee.org.nz/PUBS/2006AISBEGUIDELINES\\_Corr\\_06a.pdf](http://www.nzsee.org.nz/PUBS/2006AISBEGUIDELINES_Corr_06a.pdf).  
320 NZ Parliament (2004). "Building Act 2004." Wellington, New Zealand, New Zealand Government,  
321 M.O.E.D. Department of Building and Housing - Te Tari Kaupapa Whare. Retrived from:  
322 [www.legislation.govt.nz/act/public/2004/0072](http://www.legislation.govt.nz/act/public/2004/0072).  
323 Raftery, G. M. and C. Whelan (2014). "Low-grade glued laminated timber beams reinforced using  
324 improved arrangements of bonded-in GFRP rods." *Construction and Building Materials* **52**(0):  
325 209-220.  
326 Senaldi, I., G. Magenes and J. Ingham (2012). "Damage Assessment of Unreinforced Stone Masonry  
327 Buildings After The 2010-2011 Canterbury Earthquakes " *International Journal of*  
328 *Architectural Heritage*, DOI:10.1080/15583058.2013.840688  
329 Shrive, N. G. (2006). "The use of fibre reinforced polymers to improve seismic resistance of  
330 masonry." *Construction and Building Materials* **20**.  
331 Standards Association of New Zealand. (2004). "Structural design actions, part 5-earthquake actions  
332 New Zealand." Wellington, NZS 1170.5  
333 Stratford, T., G. Pascale, O. Manfroni and B. Bonfiglioli (2004). "Shear strengthening masonry panels  
334 with sheet glass-fiber reinforced polymer." *Journal of Composites for Construction* **8**(5): 434-  
335 443.  
336 Tumialan, J., F. Micelli and A. Nanni "Strengthening of Masonry Structures with FRP Composites."  
337 *Structures 2001*: 1-8.  
338 Zhou, D., Z. Lei and J. Wang (2013). "In-plane behavior of seismically damaged masonry walls  
339 repaired with external BFRP." *Composite Structures* **102**(0): 9-19.

340

341

342 **Figure 1.** GHS building at Arts Centre of Christchurch

343 **Figure 2.** Details of GFRP retrofit implemented at the GHS building

344 **Figure 3.** Installation of GFRP retrofit at the GHS building in 2007

345 **Figure 4:** External and internal views of the SCC building, 10 Shirley Road, Christchurch

346 **Figure 5:** Floor plan of the SCC building showing retrofit locations (highlighted) as well as the direction  
347 and location of previous/subsequent figures

348 **Figure 6:** Installation of GFRP retrofit at SCC building (photos taken in 2009)

349 **Figure 7.** North elevation of the Boys' High School building pre and post 22<sup>nd</sup> February 2011  
350 earthquake. Note the collapse of the turret and gable end walls

351 **Figure 8.** Observed earthquake damage in the Boys' High School building

352 **Figure 9.** Post-earthquake damage observations in GHS building

353 **Figure 10.** Observed performance of GFRP retrofitted walls at SCC building (photos b-f taken  
354 November 2012)

355 **Figure 11.** Observed damage to walls at SCC building having no GFRP retrofit